



A smart way to save a connector when a fiber breaks inside a ferrule during connectorization. Also an excellent tool to remove broken fiber from bare fiber adapters. Sticky colored tabs provided to hold wire.

SPECIFICATIONS

Wire Diameter

0.004" (110µm)

Length

3 inches